UNCLASSIFIED

AD 295 584

Reproduced by the

ARMED SERVICES TECHNICAL INFURMATION AGENCY
ARLINGTON 12, VIRGINIA



UNCLASSIFIED

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U.S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.

COATING and CHEMICAL MEDICAL LABORATORY



CCL REPORT NO. 136

EXPLORATION OF NEW METHODS FOR PREVENTING GALVANIC


CORROSION BETWEEN MAGNESIUM AND STEEL

BY

LT. DONALD K. STELLING

AMCHS CODE NO. 5026.11.84205 DA PROJECT 593-32-007

8 JANUARY 1963



ABERDEEN PROVING GROUND
MARYLAND

DESTROY; DO NOT RETURN

CATALOGED BY ASTIA
AS AD NO.

ASTIA AVAILABILITY NOTICE

Qualified requesters may obtain copies of this report from the Armed Services Technical information Agency, Arlington Hall Station, Arlington 12, Virginia.

Copies available at Office of Technical Services, \$ 0.50

THE FINDINGS IN THIS REPORT ARE NOT TO BE CONSTRUED AS AN OFFICIAL DEPARTMENT OF THE ARMY POSITION.

TABLE OF CONTENTS

	Paga No.
TITLE PAGE	11
ABSTRACT	611
INTRODUCTION	1 - 2
DETAILS OF TEST	2 - 3
DISCUSSION	3
SUMMARY	3 - 4
REFERENCES	4
APPEND IX.	5
Tables - V	6 - 8
nicto initiam i ist.	a <u> </u>

UNCLASSIFIED

Report No. CCL # 136	
Copy Number	

EXPLORATION OF NEW METHODS FOR PREVENTING GALVANIC CORROSION BETWEEN MAGNESIUM AND STEEL

Ву

Lt. Donald K. Stelling

8 January 1963

AMCMS Cude No. 5026.11.84205

Dept of the Army Project No. 593-32-007

Coating and Chemical Laboratory
Aberdeen Proving Ground
Haryland

UNCLASSIFIED

AUTHOR:

THE STATE OF

DONALD K. STELLING, Chemist 2nd Lt. Ord. Corps

Paint, Varnish & Lacquer Branch

REVIEWED BY: MeL

MELVIN H. SANDLER Chief, Paint, Varnish & Lacquer Branch

APPROVED BY:

C. F. PICKETT, Technical Director Coating and Chemical Laboratory

ABSTRACT

An investigation was conducted to explore new methods of treating magnesium-steel couples after the two metals had been assembled and placed in electrical contact 'the each other. A phosphate anodizing treatment, prepared with this objective in mind, proved to be ineffective when applied to such couples. The treatment seemed to offer considerable corrosion resistance to magnesium alone when the operating conditions of the treatment were controlled within close limits.

1. INTRODUCT:UN

The accelerated corrosion rate observed with magnesium when coupled to a dissimilar metal is a problem of great concern to the defense industry. With missile systems and lightweight airborne equipment becoming increasingly more complex, design requirements oftentimes call for an assembly of dissimilar metals, such as magnesium and steel. Electrical contact between the two metals is oftentimes established and because of the difference in the relative positions of the two metals in the EMF series, a galvanic cell is created. When the assembly is exposed to moisture and electrolyte, as in a saline atmosphere, galvanic corrosion results. The most effective method of preventing galvanic corrosion is to insulate the faying surfaces of the two metals to prevent the formation of the galvanic cell. However, when press fits between dissimilar metals are required, this is not possible. There is a need for an effective treatment that can be applied to dissimilar metal couples (particularly magnesium and steel) after assembly that will prevent or appreciably retard the affects of galvanic corrosion. A recently developed stannate treatment offers a step in this direction. The treatment involves immersing a magnesium-steel assembly for a minimum of twenty minutes in a bath containing potassium stannate (K_2SnO_3) , sodium hydroride (NaOH), sodium acetate $(NaC_2H_3O_2)$, and tetrasodium pyrophosphate (Na4P2O7) maintained between 180°F and 212°F. Although the treatment affords some protection against galvanic corrosion, it has not provided the desired degree of protection.

A hypothesis exists stating the rate of corrosion of a metal depends, in most cases, on the permeability of the surface film to the reactants. The porosity of the film appears to depend on the relative volume of the film compared to the volume of the metal from which it is formed, i.e, Wd/awD where:

- W = molecular weight of the metallic compound forming the film (of formula MaXb)
- D = density of the compound forming the film
- W = atomic weight of metal
- d = density of the metal
- M = metal anion of the compound forming the film
- X = cation of the compound forming the film
- a = number of anions per molecule of film compound
- b = number of cations per molecule of film compound

If this ratio is greater than one, the film tends to be protective; if the ratio is less than one, the film is porous and non-protective. The ratio for magnesium oxide (MgO), formed on a magnesium surface when exposed to moisture, is 0.64 and thereby accounts for the non-protective character of the film formed by corrosion product. On the other hand, magnesium treated with chromic acid forms a corrosion resistant film composed of magnesium chromate (MgCrO $_{\rm L}$.7H $_{\rm 2}$ O) for which the ratio is 11.3. Similarly, the film of magnesium fluoride (MgF $_{\rm 2}$) formed when magnesium is treated by hydrofluoric acid produces a ratio of 1.49 indicating the film to be protective which indeed it is.

If this hypothesis is valid for all films, then a magnesium surface film of magnesium phosphate $(\text{Mg}_3(\text{PO}_4)_2)$, resulting from treatment with a $\text{PO}_6\equiv$ solution, or a magnesium surface film of magnesium pyrophosphate $(\text{Mg}_2\text{P}_2\text{O}_7)$, resulting from treatment with $\text{P}_2\text{O}_7^{\text{magnesium}}$ solution, should be protective since their

ratios are 4.0 and 3.9 respectively. Therefore, it was decided to conduct a number of laboratory tests whereby magnesium panels would be treated by phosphate and pyrophosphate solutions under various operating conditions including the application of an external EMF. If, a treatment could be developed that would successfully protect magnesium alone, it would then be tested on magnesium-steel couples since the phosphate and pyrophosphate treatments should also produce protective films on steel because the ratios for ferrous phosphate (Fe₃ (PO₄)₂) and (Fe₄ (P₂O₇)₃) are 8.9 and 12.0 respectively.

11. DETAILS OF TEST

These studies were conducted testing the applicability of various phospheting procedures on magnesium. After treatment, the panels were coated with 0.001 inch dry film of Military Specification MiL-P-15930 (Primer, Vinyl Zinc Chromate Type, Formula No. 120) air dried 72 hours, scored, and then exposed to 20% sait spray (operated according to Federal Test Method Standard No. 141, method 6061). The test panels were examined every 24 hours and evaluated for corrosion resistance.

initially, three series of AZ31B magnesium alloy panels were given a light zinc phosphating treatment according to Military Specification TT-C-490, type 1. For each series of panels, the application procedure was varied slightly (see Table 1).

Another test (Table II) was conducted whereby two series of AZ31B alloy panels were spray treated by phosphating solutions conforming to Military Specification TT-C-490, type II.

A number of cursory laboratory tests were also performed whereby magnesium panels were treated by solutions of NaH2PO4 under various operating conditions including the application of an external EMF. Tests involving baths containing Na2P2O7 and mixtures of Na2P2O7 with NaH2PO4 were also conducted. The results of this effort showed that an anodizing bath containing NaH2PO4.H2O at a concentration of 13.7 gms/liter offered the most promising results. The phosphite anodizing process consisted of connecting the magnesium component to the anode of a D. C. source and using one or two steel plates immersed in the bath as the cathode. A current density of 16 amps/sq.ft. was applied for a period of ten minutes during which time the potential remained rather steady around 20 volts, dropping possibly a maximum of two volts. The bath was maintained at room temperature and the pH rose during the operation from about 5.0 to 5.5 where it reached a plateau. Studies were made to determine the operating limits by varying the bath concentration between 0.5 to 1.0 moles NaH2PO4/liter of water, the pH from 4.3 to 6.9, the current desnity from 8 amps/sq.ft. to 60 amps/sq.ft. and operating times from 8 to 25 minutes (see Table III).

This phosphate anodizing treatment was compared with three other proprietary magnesium treatments used quite extensively in industry, namely a chemical pretreatment conforming to Specification MIL-M-3171, Type III; an anodic pretreatment conforming to Specification MIL-M-45202 (Ord), type I, clars C; and a chemical treatment consisting of a five minute immersion at room temperature in a bath containing chromic acid (CrO₃) and calcium sulfate (CaSO₄) (see Table IV).

The phosphate anodizing treatment was also evaluated on magnesium-stee: couples. Test specimens were prepared by placing a steel bolt through a magnesium panel and treating the specimen after assembly (see Table V).

III. DISCUSSION

The TT-C-490, type I zinc phosphate immersion produced a loose, powdery coating bluish-gray in appearance. Upon removal of the powder, a dark, adherent coating was noticed on the immediate surface. The spray zinc phosphate treatment produced a coating that was free from the powdery deposit and similar in appearance to the dark undercoating of the immersion treated panels. The salt spray results shown in Table I indicate that the immersion treatment offers only slight corrosion resistance whereas the spray method offers none.

The TT-C-490, type II treatment produced only slight discoloration on the panel surfaces. The results in Table II show that the four minute spray method afforded considerably more protection than th. two minute spray.

The phosphate anodizing treatment produces a surface film which is dark & grainy in appearance. Unfortunately, the bath becomes readily depleted and in doing so, a white, powdery precipitate forms on the edges of the test panels giving the appearance of corrosion product. This precipitate is easily washed off upon subsequent rinsing and seems to have no detrimental effects upon the performance of the coating, nevertheless, it produces a rough, uneven surface. This same observation was made when the bath was operated at a high pH around 6.8, even though exc. lient corrosion resistance was noted (see Table III). This effect became worse upon subsequent treatments in the same bath. In fact, it was found that operating conditions varying slightly from a pH of 4.3 to 5.5, a current density of 16 amps/sq.ft., and an operating time of 10 to 15 minutes made the treatment considerably less effective.

When strict control over the operating variables is exercised, however, this phosphate anodizing treatment seems to offer considerable protection to magnesium alone. As can be seen in Table IV, when compared with three proprietary treatments, it offered the best corrosion resistance, being somewhat better than MIL-M-45202 and considerably better than MIL-M-3171 and the chromic acid/calcium sulfate immersion treatment.

Unfortunately, the phosphate anodizing treatment is not applicable to magnesium-steel couples. The results in Table V demonstrate the ineffectiveness of the treatment for such applications.

IV. SUMMARY

Although the phosphate anodizing treatment has been demonstrated to be non-applicable to magnesium-steel couples, further testing and development should be conducted before it can be accepted as an effective procedure for magnesium alone. Such efforts should be concentrated in(a) determining more closely the operating limits of the bath, (b) evaluating more extensively the effectiveness of the treatment by comparing it with many proprietary treatments, (c) aliminating the deposit of white precipitate on the edges of the test panels and increasing the life of the phosphate bath.

Of course the greatest efforts in future studies should be directed to devolop a method of preventing galvanic corrosion. The ideal treatment would be one that contains a self-healing ingredient which, when the film is scored, would leach out of the coating and treat the newly exposed metal. Without this particular feature, it would be thermodynamically impossible for a scored bimetallic assembly to resist corrosion.

Because of the difficulty encountered in attempting to develop an aqueous treatment for magnesium-steel couples, a study should be initiated into the use of organic media for treating bimetallic assemblies. Such a study would involve much basic research since limited information can be found in this field.

V. REFERENCES

- 1. Military Specification MiL-P-15930 Primer, Vinyi-Zinc Chromate Type (Formula 120).
- 2. Federal Test Method Standard No. 141 Paint, Varnish, Lacquer and Related Materials, Methods of Inspection, Sampling and Testing.
- 3. Military Specification TT-C-490 Cleaning Methods and Pretreatment of Ferrous Surfaces for Organic Coatings.
- 4. MIL-M-3171 Magnesium Alloy, Processes for Corrosion Protection of
- 5. MIL-M-45202 (Ord) Magnesium Alloys, Anodic Treatment of.

APPENDIX

TABLE I SALT SPRAY RESULTS (HOURS TO FAILURE)

PHOSPHATE PRETREATMENT TT-C-490, TYPE | ON MAGNESIUM

One minute @ 180°F Five minutes @ 180°F One minute @ 150°F |
Ho Pretreatment Immersion process Immersion process Spray process

24 72² 96² 24
24 72² 72² 24

TABLE II
SALT SPRAY RESULTS (HOURS TO FAILURE)

PHOSPHATE PRETREATMENT TT-C-490, TYPE II ON MAGNESIUM Two minutes @ 150°F Four minutes @ 150°F No Pretreatment Spray process Spray process 24 96 120 24 72 144 96 216 96 216 144

After pretreatment test panels were coated with the mil dry film of primer conforming to Specification MIL-P-15930, Primer, Vinyl Zinc Chromate Type, Formula No. 120.

²The loose powdery crystals formed on the surface by the immersion process were removed prior to application of primer.

After pretreatment test panels were coated with one mil dry film of primer conforming to Specification MIL-P-15930 Primer, Vinyl Zinc Chromate Type, Formula No. 120.

TABLE !!!
SALT SPRAY RESULTS

PHOSPHATE ANODIZING ON MAGNESIUM

NaH ₂ PO _L Concentration (moles/liter)	pH	Current density (amps/sq.ft.)	Operating time (minutes)	Tomperature °F	Hours Exposure Before Failure
0.1	5.0	8.0	15	74	600
0.1	4.3	16.0	10	73	912
0.1	6.8	16.0	15	72	1008
0.1	6.9	24.0	10	74	912
0.5	4.0	16.0	15	73	792
0.5	4.4	60.0	8	75	600
0.1	4.3	16.0	10	75	792
0.1	5.0	12.0	25	77	600
0.1	5.0	12.0	2 0	78	600
0.1	5.4	12.0	20	80	552
0.1	5.5	16.0	10	82	912
0.1	5.5	16.0	10	82	792

After pretreatment test panels were coated with one mil dry film of primer conforming to Specification MIL-P-15930 Primer, Vinyl Zinc Chromate Type, Formula No. 120.

TABLE IV
SALT SPRAY RESULTS (HOURS TO FAILURE)

PHOSPHATE ANODIZE VS PROPRIETARY PRETREATMENTS ON MAGNESIUM

No Pretreatment	Phosphate anodize ²	MIL-M-3171 Type III	MIL-M-45202(Ord) Type I, Class C	Cr0 ₃ +CaSსც ³ Bath
72	648	168	360	168
72	744	216	672	216
72	720	168	672	168
72	648	240	408	240
72	648	240	408	240
72	648	216	672	216

After pretreatment test panels were coated with one mil dry film of primer conforming to Specification MIL-P-15930 Primer, Vinyl Zinc Chromate Type, Formula No. 120.

²Operating conditions: 0.1 mole/liter; pH = 5.0 to 5.5; current density 16 amps/sq/ft/; operating time 10 min. at room temperature.

³Five minute immersion in the bath at room temperature.

TABLE V
SALT SPRAY RESULTS (HOURS TO FAILURE)

PHOSPHATE ANODIZE ON MAGNESIUM-STEEL COUPLE			
No Pretrestment	Phosphate Anodiza ²		
24	24		
24	24		
* 2 4	24		
2/+	24		
24	24		
24	24		

Specimens were assembled prior to treating. After pretreatment they were coated with one mil dry film of primer conforming to Specification MIL-P-15930 Primer, Vinyl Zinc Chromate Type, Formula 120.

²Operating conditions: 0.1 mole/liter; pH 5.0 to 5.5, current density 16 amps/sq.ft. Operating time - 10 minutes at room temperature.

DISTRIBUTION LIST FOR AMCHS CODE 5026.11.842

Department of Defense	No. of Capie
Arms Services Technical Information Agency Arlington Hall Station Arlington 12, Virginia	10
Department of the Army - Technical Service	
Commanding General	
U.S. Army Materiel Command	
ATTN: AMCORTB	1
Washington 25. D. C.	
Continental Army Command	
Department of the Army	3
Fort Monroe, Virginia	
Commanding General	
U.S. Army Mobility Command	
U.S. Army Tank-Automotive Center	•
ATTN: Mr. J. P. Jones Mr. V. Pogano	
Center Line, Michigan	•
Commanding Officer	
U.S. Army Munitions Command	
ATTN: SMUFA 1320	1
Library	1
Philadelphia 37, Pa.	
Commanding Officer	
U.S. Army Materials Research Agency	
Watertown Arsenal	
ATTN: Technical Information Center	2
Watertown 72, Mass.	
Commanding Officer	
Harry Diamond Laboratory	
ATTN: Library	ì
Washington 25, D. C.	
Commanding Officer	
U.S. Army Test Activity	_
Yuma Test Activity Yuma, Arizona	ì
Commanding Officer	
U.S. Army Munitions Command	
Picatinny Arsenal	
ATTN: Mr. J. J. Begley	1
Dover. New Jersey	•

DISTRIBUTION LIST CONTINUED

	No. of Capies
Commandin ifficer	
U.S. Army Ballistic Research Laboratories ATTN: Mr. W. C. Pless	•
Mr. R. Elchelberger	i 1
Mr. J. Sporrazza	1
Aberdeen Proving Ground, Maryland	
Technical Library	
Aberdeen Proving Ground, Maryland	2
Department of the Nevy	
Department of the Navy	
c/o Navy Liaison	1
Aberdeen Proving Ground, Maryland	
Commander	
U.S. Naval Weapons Laboratory	1
Dahlgren, Virginie	
Department of the Navy	
Chief, Burcau of Naval Weapons	1
Washington 25, D. C.	
Other Government Agencies	
Scientific and Technical Information Facility	
ATTN: NASA Representative (S-AK/DL)	
P. O. Box 5700	3
Bethesda, Maryland	
Office of Technical Services	
Acquisitions Section	100
Department of Commurce Washington 25, D. ().	
washington 25, 50 th	
Foreign Address	
Ministry of Supply Staff	
British Joint Services Mission	
1800 K Street, N. W. Washington 6, D. C.	2
washington o, o. c.	
Canadian Army Staff	
ATTN: GSO-1 A&R Section 2450 Massachusetts Avenue, N. W.	2
Washington A. D. C.	4

AD NO COASTON NO COASTON NO COASTON NO COASTON SECURAL. CCL. # 135 - EXPLOR-ATION OF NEW METHODS FOR PREVENTING GALVANIC CORROSION BETWEEN MAGNESIUM AND STELL - Lt. Dowald K. Stelling, Rpt No. 136, 8 January 1963, 13 pgs, AMCHS Code 5026.11.84205, DA Proj No 593-32-007 An investigation was conducted to explore new methods of treating magnesiumstel couples after the two metals had been assembled and placed in electrical contact with each other. A phosphate anodizing treatment, prepared with this	objective in mind, proved to be ineffective when applied to such couples. The AD No Coating & Chemical Laboratory, Aberdeen Proving Ground, Md., CCL # 136 - EXPLOR-ATION OF NEW NETHODS FOR PREVENTING GALVANIC CORROSION BETWEEN MAGNESIUM AND STEEL - Lt. Donald K. Stelling, Ppt No. 136, 8 January 1963, 13 pgs, AMCMS Code 5026.11.84205, DA Proj No 593-32-007	An investigation was conducted to explore new methods of treating magnesium steel couples after the two metals had been assembled and placed in electrical contact with each other. A phosphate anodizing treatment, prepared with this objective in mind, proved to be ineffective when applied to such couples. The
Unclassified	Unclassified	•
Unclass i fied	Unclassified	
AD No Coating & Chemical Laboratory, Aberdeen Proving Ground, Nd., CCL # 136 - EXPLORATION OF NEW METHODS FOR PREVENTING CALVANIC CORROSION BETWEEN MAGNESIUM AND STEEL - Lt. Bonald K. Stalling, Rpt No. 136, 8 January 1963, 13 pgs, ANCMS Code 5C26.11.84205, DA Proj No 593-32-007 An investigation was conducted to explore now methods of treating magnesiumsteel couples after the two metals had been assembled and placed in electrical contact with each other. A phosphate	objective in mind, proved to be ineffective when applied to such couples. The AD Mo Coating & Chemical Laboratory, Aberdeen Proving Ground, Md., CCL # 136 - EXPLORATION OF NEW METHEN MAGNESIUM AND TIFEL - Lt. Donald K. Stelling, Rpt Mo. 1758, 8 January 1963, 13 pgs, ANCMS Code 1753, 13 January 1963, 13 pgs, ANCMS Code 1753, 13 January 1963, 13 pgs, ANCMS Code	An investigntion was conducted to explore new methods of treating magnesium steel couples after the two metals had been assembled and placed in electrical contact with each other. A phosphate anodizing treatment, prepared with this objective in mind, proved to be ineffective when applied to such couples. The

.

f .

	resistance to magnesium alone when the operatory of the treatment were controlled within close limits.	Unclassified	treatment seemed to offer considerable corrosion resistance to magnesium alone when the operating conditions of the treatment were controlled within close limits.
Unclassified treatment seemed to offer considerable corrosion	resistance to magnesium alone when the operating conditions of the treatment were controlled within close limits.	Unclassified	resistance to magnesium alone when the operating conditions of the treatment were controlled within close limits.